Structure Saint Mark's Episcopal Church (TEX-33)

307 E. Pecan St. Limestone ashlar, steep gable roof over nave, breaking to lesser pitch over the aisles; low buttresses; stone tracery in segmental pointed-arched windows. Unusual breadth and lightness in interior construction. Gothic Revival. Architect, Richard Upjohn. Construction began with cornerstone laying on December 22 1859. Walls had reached a height of seven feet at the outbreak of the Civil War, which halted all work until (over)

Form 10-444 (2/62)

TORIC AMERICAN BUILDINGS SURVEY

March 1873. The first services in the completed church were held on Easter Sunday, 1875. 4 ext. photos (1936); 3 data pages (1936); HABSI.

Card prepared July 1975.

Ref: San Antaina & Spress Files,